



# Drives & Nutrunners



Paragon now offers Atlas Copco Power Focus repairs. All controllers will have the power supply and memory battery replaced.

All the controller boards are tested and calibrated to full OEM specifications before leaving Paragon.

Paragon also has the capabilities to test all S4, S7 and S9 nutrunners. Upon repair before leaving Paragon, all nutrunners are also tested and calibrated to full OEM specs.

## DRIVES

### ATLAS COPCO

#### Tenor DS

D302-DS7

D312-DS7

### ATLAS COPCO

#### Tenor S (2000)

Power Focus 2101-S4

Power Focus 2102-S4

Power Focus 2101-S7

Power Focus 2102-S7

Power Focus 2102-S9

## NUTRUNNERS

### ATLAS COPCO

#### Tenor DS

ETV-DS7

ETF-DS7

ETD-DS7

ETP-DS7

ETC-XXX

ETO-XXX

### ATLAS COPCO

#### Tenor S

ETV-XXX

ETF-XXX

ETD-XXX

ETP-XXX

ETC-XXX

ETO-XXX

### TECH MOTIVE

#### CS7000

17710-XXXX

17711-XXXX

27711-XXXX

27712-XXXX

27713-XXXX



5775 Ten Mile Road  
Warren, MI 48091  
phone: (800) 229-5350  
fax: (800) 229-5375  
www.paragontech.com



1100 South Service Rd., #103  
Stoney Creek, ON., Canada L8E 0C5  
phone: (800) 567-3786  
fax: (800) 229-5375  
www.paragoncanada.ca



2919 Interstate Street  
Charlotte, NC 28208  
phone: (800) 756-9150  
fax: (800) 229-5375  
www.paragonatlantic.com



82 Corporate Park Drive  
Henderson, NV 89074  
phone: (800) 756-9160  
fax: (800) 229-5375  
www.paragonpacific.net